

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

Site/Project Name: Ja- To-K Holsteins (Pane Mercer)								NPDES Tracking Number:				
Street Address or Location: 451 Randolph Fridley Road, In. 378								Date Coverage was Issued				
Str	eet Address or	0 1115	1/	0	1	SWEET	rister	Start date:		7/28/13		
Lo	cation: 95/	Kandolph F	ridley	100	1	Th.	37874	Estimated		11.4		
Sit	e / Hi		/									
Site Description: Lattle Cagain									Longitude (-dd.dddd): -89,4104 74			
MCA								Acres Disturbed: 2.77				
Cu	unty(ies): Monroe		Jurisdic					Total Acres	s:	2.71		
	me of Permittee (Developer/		- Hulst	eihr							423-	
Name of Official Contact: Vane Morcer Email:											1e: 519-710	
Ad	dress: 451 Randolp	L Fridley Rd	City: Si	vee Tv	1 wher					State: Tn	Zip: 37874	
Cho	ck List (office & field checks)	F. Committee	20000	Yes	No			(Comme	nts	Part of the second	
1	Does the site have CGP cov	erage?			Ш	ļ						
2	Is NOC posted on site?											
3	Have the site contractors signed the NOI?			V	Ш							
4	Is the current SWPPP available for review?			V)								
5	Are EPSCs in accordance with SWPPP?											
6	Are EPSCs installed properly and functional?											
7	Are inspection reports available on site?				Ш							
8	Is the proper buffer zone maintained?				Ш							
9	Were there unstable, inactive areas on the site? If so, does inspector know if length of time has been more than 14 days (or 7 days for steep slopes)?					ľ.						
_0	Are more than 50 acres distu			157	Til.	1//A						
11	Has sediment discharged off site?				17	1,0,71						
12	Has sediment discharged into waters of the State?				10							
13	Are there unauthorized alterations to waters of the State?				T	1						
14	Are there violations of an existing ARAP?				174	1						
	If so, ARAP No.?					 						
15					L	-						
16	Project is complete and stable with no construction-related stormwater discharges?				Ш	. 8						
Ger	neral Comments:				х	4.						
						12						
										~		
			((6)									
		*										
	Routine 🗹	Comprehensive	digitary stre	Cor	nplaint		100000	Follow U	0.6	Termin	ation 🔲]	
	Site Contact (if available)	90.185	G: 4				1.000		Insta			
On-Site Contact Name (Print): On-Site Contact Title:			Signa			e:			Date:			
wn:	C Personnel/Information		N/88, v4/140	All S		397/459	77			EFO: Name a	nd Address	
spector's Name (Print): Signature;							Date: /	1-2-15	1-7-15 Kn		oxville Environmental Field Office	
Alle Willinson Alle Ville			la	>					3711 Middlebrook Pike Knoxville, TN 37921			
()	UVIA WILLIAM			er c	_		Time:	11:20	1,7000		SEVERAL SEVENCE	